

Other Options

[Return to menu](#)
[Plot this site in State Library Digital Atlas](#)
[Plot this site in Google Maps](#)
[View scanned well log \(7/23/2009 12:37:55 PM\)](#)

Section 7: Well Test Data

Total Depth: 26.5

Static Water Level: 9.2
Water Temperature:

Pump Test *

Depth pump set for test feet.
60 gpm pump rate with feet of drawdown after 2.5 hours of
pumping.
Time of recovery 0.03 hours.
Recovery water level 9.2 feet.
Pumping water level 10.3 feet.

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Section 8: Remarks

Section 9: Well Log

Geologic Source

Unassigned

[illegible]

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

From	To	Diameter
0	25.5	6

Annular Space (Seal/Grout/Packer)

From	To	Description	Cont. Fed?
0	0	BENTONITE	

Name: Company: ERICKSON DRILLING & PUMP CO License No: WWC-478 Date Completed: 10/22/2000
--